



Excellence at work. Excellence in life.

Repair Kit for KT850

Repair Kit: 820088 0850

Description	Part Number	Quantity
BOX PACKAGING 28"X20"X12"	18877-282012	1
INSTRUCTION SHEET-KT850-PISTON/CAM	2020-0850-6	1
CAM,OUTER T00850	808282 C000	2
PISTON,OUTER T00850	807565 C000	2
PISTON,CENTER T00850	807564 C000	1
CAM,CENTER T00850	808283 C000	1
--SQ. SOCKET PIPE PLUG 2 NPT CAST IRON	057180 00CI	8
CASTING, IRON, CAM,OUTER T0850C	818282 0CST	2
CASTING, IRON, PISTON,OTR,STR RLV T0850	817565 0CST	2
CASTING, IRON, PISTON,CTR,STR RLV T0850	817564 0CST	1
--SQ. SOCKET PIPE PLUG 2 NPT CAST IRON	057180 00CI	4
CASTING, IRON, CAM,CENTER T0850C	818283 0CST	1

Updated: 7/22/2014 SR