

KMBD 850C/1200C/1600C/2000C/2700C Repair & Maintenance Kit

The following list of parts, headed by Tuthill Vacuum & Blower Systems Model Number, are the recommended spare parts to overhaul the unit.

Prices quoted are Ex Works, Springfield, MO USA. Minimum order \$50.

Slinger Seal, C-flange Booster Kit - P/N 55272 (Old P/N 809288 00BM)

<u>Description</u>	Part Number	Quantity
Gear Lock Plate	55325	2
Ball Bearing	10999-D	2
Roller Bearing	29252	2
Lip Seal	11684	1
Timing Gear Shim	55357	1
Gear Key	11200	2
Cap Screw	90295-100	1
Cap Screw	92241-050	6
Lockwasher	5879	2
Lab Seal	23495	4
Mechanical Seal	11449	4
Lock Plate	11057	6
Lock Plate	10925	2
Cap Screw	90295-175	1
Mechanical Seal	55014	1
O-Ring	29361-244	1
Shim	55239	5

The following part(s) are listed for reference only and are not a part of the repair kit:

Gear Assembly 29605 1

11/2004 dt